US ERA ARCHIVE DOCUMENT

Situation U	Ralamazoo River/Enbridge Oil gnators Unit  S. Unit Leader (Name and Position) Melinda Luetke, Plant  Personr Name ICS Positi arry Rader Situation Unit Activity  verflight Operational status:  Source area pond: No sheen observed. Frac-Tank City: observed the timber mate	ning Section Chief nel Roster Assigned ion Leader	1600 6. Operational Period 0700, 06/07/12 – 0700, 06/14/12  Home Base Chicago, Illinois
La 3.	Personr Name ICS Positi arry Rader Situation Unit Activity verflight Operational status:  Source area pond: No sheen observed. Frac-Tank City: observed the timber mate	nel Roster Assigned ion Leader Log	0700, 06/07/12 – 0700, 06/14/12 Home Base
La S.	Personn Name ICS Positi arry Rader Situation Unit Activity verflight Operational status:  Source area pond: No sheen observed. Frac-Tank City: observed the timber mate	nel Roster Assigned ion Leader Log	0700, 06/14/12 Home Base
La 3.	Name ICS Position arry Rader Situation Unit  Activity  verflight Operational status:  Source area pond: No sheen observed. Frac-Tank City: observed the timber mate	Leader Log	Home Base
La	Name ICS Position arry Rader Situation Unit  Activity  verflight Operational status:  Source area pond: No sheen observed. Frac-Tank City: observed the timber mate	Leader Log	
Time	verflight Operational status:  Source area pond: No sheen observed. Frac-Tank City: observed the timber mat	Leader Log	
Time	verflight Operational status:  Source area pond: No sheen observed. Frac-Tank City: observed the timber mat	Log	Chicago, Illinois
Time	verflight Operational status:  Source area pond: No sheen observed. Frac-Tank City: observed the timber mat		
	<ul> <li>verflight Operational status:</li> <li>Source area pond: No sheen observed.</li> <li>Frac-Tank City: observed the timber mat</li> </ul>	Major Events	
11:00 Ov	<ul><li>Source area pond: No sheen observed.</li><li>Frac-Tank City: observed the timber mat</li></ul>		
	· Frac-Tank City: observed the timber mat		
	· Frac-Tank City: observed the timber mat		
		ts being disposed of	
	<ul> <li>Confluence: no sheen or turbidity observ</li> </ul>		
	<ul> <li>Poling crew observed along RDB adjace</li> </ul>		
	<ul> <li>MP5.25 LDB Lily Pad area: no sheen ob</li> </ul>		
	· Ceresco Dam: boom maintenance crew r		rol point.
	Sheen and turbidity observed.	<u> </u>	•
	<ul> <li>Turbidity plume observed above Ceresco</li> </ul>	Dam.	
	· Poling crew observed in water near MP		
	• MP10.75 Sediment trap: No sheen obser		
	• Sweeper boat observed at south end of M		
	<ul> <li>Poling Crew and sweeper boat observed Ponds.</li> </ul>	_	in Mill
	<ul> <li>Battle Creek Spillway and Mill Ponds. N</li> </ul>		
	<ul> <li>Possible submerged boat observed in rive</li> </ul>		
	Poling crew observed at MP19.25 sedim	-	
	• MP24.5 RDB, poling crew observed in b		
	• MP28.25 back channel, sheen observed.		
	• MP30.8, no sheen observed within the be		
	<ul> <li>Poling crew observed at east end of Mor</li> </ul>	row Lake Delta.	

Larry Rader, Situation Unit Leader, USEPA-START